





| HUS3-P | h <sub>1</sub>           | h <sub>1</sub>           | t <sub>fix</sub> |
|--------|--------------------------|--------------------------|------------------|
| 6 x 40 | 50 mm – t <sub>fix</sub> | 43 mm – t <sub>fix</sub> | 0 ... 5 mm       |
| 6 x 60 | 70 mm – t <sub>fix</sub> | 63 mm – t <sub>fix</sub> | 5 ... 25 mm      |
| 6 x 80 | 90 mm – t <sub>fix</sub> | 83 mm – t <sub>fix</sub> | 25 ... 45 mm     |





| 1.1            |        |        |        |
|----------------|--------|--------|--------|
|                |        |        |        |
| d <sub>0</sub> | Ø 6 mm | Ø 6 mm | Ø 5 mm |



| 3.1              |                                     |                                     |                          |                          |
|------------------|-------------------------------------|-------------------------------------|--------------------------|--------------------------|
| h <sub>nom</sub> | 35 mm                               | 55 mm                               | 55 mm                    | 55 mm                    |
|                  | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
|                  | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
|                  | <input type="checkbox"/>            | <input type="checkbox"/>            | <input type="checkbox"/> | <input type="checkbox"/> |
|                  | 18 Nm                               | 25 Nm                               | 12 Nm                    | 6 Nm                     |





| HUS3-P |  $h_1$ | $t_{fix}$    |
|--------|---|--------------|
| 6 x 40 | 43 mm – $t_{fix}$   | 0 ... 5 mm   |
| 6 x 60 | 63 mm – $t_{fix}$   | 5 ... 25 mm  |
| 6 x 80 | 83 mm – $t_{fix}$   | 25 ... 45 mm |

